

Historic Preservation Services

Community Development & Neighborhood Services 281 North College Avenue P.O. Box 580 Fort Collins, CO 80522.0580

970.416.4250 preservation@fcgov.com fcgov.com/historicpreservation

REPORT OF ALTERATIONS TO DESIGNATED RESOURCE AMENDMENT ADDRESSING PROJECT MODIFICATIONS Site Number/Address: 600 Mathews St. Laurel School National Register Historic District ISSUED: December 10, 2020

Susan and Douglas Naffziger 600 Mathews St. Fort Collins, CO 80524

Dear Mr. & Mrs. Naffziger:

This report is to document the summary of effects from proposed alterations to the E.D. Ball Residence at 600 Mathews Street, pursuant to Fort Collins Municipal Code Chapter 14, <u>Article IV</u>, made by the Landmark Preservation Commission (LPC) at their May 13th meeting. It has been revised by staff on December 10, 2020 to acknowledge alterations to the project in response to floodplain mitigation. A copy of this report may be forwarded to the Colorado Office of Archaeology and Historic Preservation.

The Commission commented on the following work items on May 13:

- 1. Demolition of a portion of the c.1921 addition on the east side of the main house;
- 2. Construction of a new addition on the east side of the main house;
- 3. Replacement of exterior windows with metal clad wood replacements.
- 4. Infill of north-facing doorway on porch
- 5. Demolition and reconstruction of concrete porch floor
- 6. Construct new guardrail of powder-coated metal
- 7. In-kind roof replacement (asphalt shingle) *Since this item clearly meets the Standards and is typically cleared by staff, it has not been included in the summary below.*

This report has been revised to reflect the following changes:

- 3. Revised to repair/rehabilitation of the historic windows.
- 8. NEW ITEM: Relocation of the main house onto a new, raised foundation, moving the building outside the currently-mapped High-Risk Floodplain.

This project update has not been referred back to the LPC because, while the modifications are significant, the relocation of the building will not have a significant overall effect on whether the building retains its contributing status in the Laurel School Historic District. Primary concerns relate to careful project planning and civil/structural engineering, which have been addressed in the revised building permit application.

Applicable Code Standard								
SOI #1	A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces, and spatial relationships;							
	The property is remaining residential in use, and will remain recognizable as a residential building.							
	NO UPDATES							
SOI #2	The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.	Y						
	 Demolition of a portion of the c.1921 addition on the east side of the main house; This addition appears to be historic, based on its construction year in relation to the period of significance suggested in the Laurel School Historic District documentation (1876-1930). A permit pulled in 1921 to remodel the home precedes the 1925 Sanborn Fire Insurance map in which the east side of the residence matches its current configuration. The remodel appears to have extended the original T-form of the home, adding a second north-south section, as well as a small bump out, likely for a kitchen or mudroom. It is the small bump out that is proposed for demolition. While minor, these are common historic features on homes of this style and type and are typically considered historic alterations that should be preserved. Its demolition does not meet this Standard. 							
	 2. <u>Construction of a new addition on the east side of the main house;</u> As noted above, the demolition of this portion of the existing c.1921 addition does not meet this Standard. 							
	 3. <u>Rehabilitation of exterior windows</u> The rehabilitation of historic windows is generally recommended unless their condition makes them unable to be repaired. Windows on this home are predominantly 							

one-over-one wood sash windows of varying sizes, although some non-historic metal storms and window units are present on the east and south elevations. In this case, the windows do not appear to warrant replacement as they are in good condition overall, although several appear to require repair. Revised plans call for repair/upgrading for energy performance. This item meets this Standard.

4. Infill of north-facing doorway on porch

• From available documentation, the second doorway was likely added as part of the 1921 remodel. Looking at city directories after that point, multiple residents are listed at the property, indicating that this may have been a modification to accommodate apartment use in the front room. Considering that this is a comparatively unique alteration in the Laurel School Historic District, and took place during the suggested period of significance for the district, removing this feature does not meet this Standard.

5. <u>Demolish and reconstruct concrete porch floor</u>

• The concrete flooring on the porch is likely not original to the home, as the porch appears to have been modified several times over the life of the home. Potentially relevant permits include two issued to "repair porch" in both 1939 and 1948. The Sanborn map in 1943 shows only a partial frame porch on the north portion of the building, indicating that the wrap-around and concrete floor was likely added in 1948. While occurring outside the period of significance, this modification is over fifty years of age and distinctive for the property. While repair is generally recommended over wholesale replacement, this item generally meets this Standard.

6. Construct new guardrail

• The installation of the guardrail is a common addition to historic homes to meet current building code and safety requirements. However, wood is a more appropriate product in these circumstances than the proposed powder-coated metal. Nearly all of the finishes on the exterior are wood. If metal is used, it would be best for it to not anchor into the wood porch columns to avoid damaging the historic carpentry. This item generally meets this Standard.

	8. Lift building off existing foundation, demolish existing	
	foundation, and relocate building south out of High-Risk	
	Floodplain	
	• The relocation of the building to the south out of the	
	High-Risk Floodplain will not significantly alter the	
	relationship of the building to its historic site. The	
	historic garage will remain south and east of the main	
	building. The primary change will be the demolition of	
	the existing stone foundation and construction of a new	
	concrete foundation for the new finished basement. This	
	item generally meets the Standard. Salvage of the stone	
	on-site is encouraged.	
SOI #3	Each property will be recognized as a physical record of its time,	Y
	place, and use. Changes that create a false sense of historical	
	development, such as adding conjectural features or elements from	
	other historic properties, will not be undertaken.	
	1. Demolition of a portion of the c.1921 addition on the east side of	
	the main house;	
	a. As noted under Standard 2, although a smaller	
	feature and not original to the house, rear additions	
	made during an historic period for kitchens or	
	mudrooms are typically considered historic and are	
	recommended for preservation. It appears the east	
	addition, along with this kitchen/mudroom, were	
	added in 1921, during the period of significance for	
	the district. It is distinctive and recommended for	
	preservation. This item does not meet this Standard.	
	2. <u>Construction of a new addition on the east side of the main</u>	
	<u>house;</u>	
	a. As noted above, the demolition of this portion of the	
	existing c.1921 addition does not meet this Standard.	
	3. <u>Rehabilitation of exterior windows</u> .	
	a. UPDATED: This item includes rehabilitation, repair,	
	and upgrade of the existing windows. This alteration	
	meets this Standard.	
	4. <u>Infill of north-facing doorway on porch</u>	
	a. As noted under Standard 2, it appears this doorway	
	was likely added along with the east addition in 1921	
	to allow the owners to let rooms to guests or students	
	at Colorado Agricultural College (now Colorado	
	State University). Removing this alteration would	
	• • •	
	eliminate a record of use during the historic period and does not meet this Standard.	
	una aves noi meet inis Stanaara.	

	5. Demolish and reconstruct concrete porch floor							
		a. Although wholesale replacement is not typically						
		recommended, this element generally meets this						
		Standard.						
		Standard.						
	6.	Construct new guardrail of powder-coated metal						
		a. As noted under Standard 2, adding new guard rails						
		are common alterations to historic homes that						
		typically meet Standards. Although wood would be a						
		more appropriate material, the proposed railing is of						
		simple design and generally meets this Standard.						
		simple action and generally meets into standard						
	8.	Lift building off existing foundation, demolish existing						
	foundation, and relocate building south out of High-Risk Floodplain							
	<i>a.</i> The new foundation will be recognizable as such due							
		to use of modern concrete. The alteration has been						
		well-documented and should avoid any false sense of						
		history, meeting this Standard.						
SOI #4	Ch	anges to a property that have acquired historic significance in	Y					
	the	eir own right will be retained and preserved.						
	1.	Demolition of a portion of the c.1921 addition on the east side of						
		the main house;						
		• As noted under Standard 2, although a smaller feature						
		and not original to the house, rear additions made during						
		an historic period for kitchens or mudrooms are typically						
		considered historic and are recommended for						
		preservation. It appears the east addition, along with this						
		kitchen/mudroom, were added in 1921, during the period						
		of significance for the district. It is distinctive and						
		recommended for preservation. This item does not meet						
		this Standard.						
	2.	Construction of a new addition on the east side of the main						
		house;						
		• As noted above, the demolition of this portion of the						
		existing c.1921 addition does not meet this Standard.						
		0						
	3.	Rehabilitation of exterior windows.						
		• <i>N/A</i>						
	4.	Infill of north-facing doorway on porch						
		• As noted under Standard 3, it appears this doorway was						
		likely added along with the east addition in 1921 to allow						
		the owners to let rooms to guests or students at Colorado						
		Agricultural College (now Colorado State University).						

	 The modification of homes to serve as apartments is an under-studied but likely significant period in the development of this neighborhood east of campus. Removing this alteration would eliminate a record of use during the historic period and does not meet this Standard. 5. Demolish and reconstruct concrete porch floor As noted under Standard 2, it is likely that the north portion of the porch was original to the home, while the east and south elements, along with the concrete foundation, were added in 1948 as part of a porch repair. Although falling outside of the period of significance, it is a distinctive architectural feature of the home that appears to have acquired its own significance. While wholesale replacement is typically not recommended, this item generally meets this Standard. 6. Construct new guardrail of powder-coated metal N/A 	
	 8. Lift building off existing foundation, demolish existing foundation, and relocate building south out of High-Risk Floodplain N/A 	
SOI #5	Distinctive materials, features, finishes, and construction techniques or examples of craftsmanship that characterize a property will be preserved.	Y
	 Demolition of a portion of the c.1921 addition on the east side of the main house; As noted above, the c.1921 addition, including the mudroom/kitchen bump-out is a distinctive alteration of buildings of this era and is typically recommended for preservation. 	
	 2. <u>Construction of a new addition on the east side of the main house;</u> As noted above, the demolition of this portion of the existing c.1921 addition does not meet this Standard. 	
	 3. <u>Rehabilitation of exterior windows</u>. b. As noted under Standard 2, the rehabilitation of historic windows is generally recommended unless their condition makes them unable to be repaired. This is largely due to the significance of historic windows to defining the character of most historic 	

buildings. Windows on this home are predominantly one-over-one wood sash windows of varying sizes. The project aims to rehabilitate existing windows and this item meets this Standard.

4. Infill of north-facing doorway on porch

• As noted under Standard 4, it appears this doorway was likely added along with the east addition in 1921 to allow the owners to let rooms to guests or students at Colorado Agricultural College (now Colorado State University). The modification of homes to serve as apartments is an under-studied but likely significant period in the development of this neighborhood east of campus. Alterations that represent significant shifts or trends are typically considered character-defining features recommended for preservation. This item does not meet this Standard.

5. Demolish and reconstruct concrete porch floor

The concrete flooring on the porch is likely not original to the home, as the porch appears to have been modified several times over the life of the home. Potentially relevant permits include two issued to "repair porch" in both 1939 and 1948. The Sanborn map in 1917 shows only a partial frame porch on the north portion of the building. The wrap-around may have been added later. It is probable the concrete flooring was added in either 1939 or 1948 along with the wrap-around expansion of the porch as it exists today. While over fifty years of age, it does not appear to have taken place during the period of significance. While wholesale replacement is typically not recommended, there are not substantial differences in the workmanship of concrete in the mid-twentieth century and current concrete methods. This item generally meets this Standard.

6. Construct new guardrail of powder-coated metal

- As noted previously, the addition of guardrails on porches for safety is a common rehabilitation method for historic buildings. While wood is typically recommended over metal, this item appears to meet this Standard.
- 8. Lift building off existing foundation, demolish existing foundation, and relocate building south out of High-Risk Floodplain

 N/A

SOI #6	Deteriorated historic features will be repaired rather than Y replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture, and, where possible, materials. Replacement of missing features will be substantiated by documentary and physical evidence.								
	 Demolition of a portion of the c.1921 addition on the east side of the main house; N/A; the demolition of this section is not based on condition. 								
	 2. <u>Construction of a new addition on the east side of the main house;</u> N/A 								
	 3. <u>Rehabilitation of exterior windows</u>. As noted previously, while several of the historic window units are in need of repair, the overall condition of the windows appears to warrant repair rather than replacement under this Standard. The proposed rehabilitation of the windows meets this Standard. 								
	 4. <u>Infill of north-facing doorway on porch</u> <i>N/A; the removal of this feature does not appear to be based on condition.</i> 								
	 5. Demolish and reconstruct concrete porch floor As noted previously, the concrete flooring on the porch is likely not original to the home, probably added in 1948 along with the entire west portion of the porch. Wholesale replacement is typically not recommended and in this case, while there are cracks in the concrete, this form of cracking is typical and can usually be repaired with epoxy sealant or a new top seal rather than full demolition. This item does not meet this Standard. 								
	 6. <u>Construct new guardrail of powder-coated metal</u> <i>N/A; the construction of this feature is not related to the condition of the property.</i> 								
	 9. Lift building off existing foundation, demolish existing foundation, and relocate building south out of High-Risk Floodplain N/A 								

SOI #7	Chemical or physical treatments, if appropriate, will be undertaken							
	using the gentlest means possible. Treatments that cause damage							
	to historic materials will not be used.	N/A						
SOI #8	0 I I I							
	If such resources must be disturbed, mitigation measures will be							
	undertaken.	X 7						
SOI #9	New additions, exterior alterations, or related new construction	Y						
	shall not destroy historic materials that characterize the property.							
	The new work shall be differentiated from the old and shall be							
	compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.							
	to protect the historic integrity of the property and its environment.							
	1. Demolition of a portion of the c.1921 addition on the east side of							
	the main house;							
	• As noted previously, the portion of the c.1921 addition							
	proposed for demolition appears to be a character-							
	defining feature and would not be recommended for							
	removal under the Standards.							
	2. Construction of a new addition on the east side of the main							
	house;							
	• The demolition of the existing portion of the home does							
	not appear to meet this Standard. But for the demolition							
	of that feature, the addition appears to meet many of the							
	requirements of additions on historic buildings under this							
	Standard. It is of compatible design, would be							
	distinguishable from the new construction and is							
	subordinate to the primary historic building. However,							
	the engineered wood product proposed for siding the new							
	addition is not typically recommended for use on historic							
	buildings due to its questionable durability compared to							
	old-growth lumber, such as that on the portion of the							
	1921 addition proposed for demolition. Furthermore, due							
	to the demolition involved, this alteration would not be							
	reversible.							
	3. <u>Rehabilitation of exterior windows</u> .							
	• <i>N/A</i>							
	4. Infill of north-facing doorway on porch							
	• As noted previously, this doorway seems likely to							
	represent an important development trend during the							
	Historic District's suggested period of significance.							
	Although likely reversible if the door is retained on-site,							
	its removal and infill would not likely meet this Standard.							

	5.	Demolish and reconstruct concrete porch floor	
		• The project proposes replacement generally in-kind, with	
		modification to south side area. This item generally	
		meets this Standard.	
	6.	Construct new guardrail of powder-coated metal	
	0.	• The proposed guardrail is of minimalist design and,	
		while wood would be recommended in this case for	
		material, the powder-coated metal should not have a	
		detrimental effect on the character of the property. This	
		item likely meets this Standard.	
	8.	Lift building off existing foundation, demolish existing	
	0.	foundation, and relocate building south out of High-Risk	
		<u>Floodplain</u>	
		• The new concrete foundation will be cleanly	
		differentiated from the historic stone foundation. The	
		raised foundation, although higher than historically used	
		for this property, is a reasonable alteration to mitigate for	
		future flood events, and is still in keeping with the	
		historic nature of this era of home construction, which	
		often included raised, partially finished basements.	
		Construction of the new basement may result in damage	
		to historic two-track driveway features on the south side	
		of the building. It is encouraged that materials are either	
		repaired, or replaced in-kind or with similar materials	
		(pavers, etc.) to preserve this distinctive driveway	
		feature. This item generally meets this Standard.	
SOI #10	Ne	w additions and adjacent or related new construction will be	Y
		dertaken in such a manner that, if removed in the future, the	
		ential form and integrity of the historic property and its	
		vironment would be unimpaired.	
		-	
	1.	Demolition of a portion of the c.1921 addition on the east side of	
		the main house;	
		• As noted previously, the portion of the c.1921 addition	
		proposed for demolition appears to be a character-	
		defining feature and would not be recommended for	
		demolition under the Standards. Demolition is not	
		reversible, so this item does not meet the Standards.	
		reversible, so mis tient does not meet the standards.	
	2.	Construction of a new addition on the east side of the main	
		house;	
		• The project proposes replacement generally in-kind, with	
		modification to south side area. This item generally	
		meets this Standard.	

3.	Rehabilitation of exterior windows
	• <i>N/A</i>
4.	Infill of north-facing doorway on porch • N/A
5.	
	 As noted previously, the construction of the deck does
	appear to be reversible, and does meet this Standard.
6.	Construct new guardrail of powder-coated metal
	• The construction of the deck does appear to be
	reversible, and does meet this Standard.
8.	Lift building off existing foundation, demolish existing
	foundation, and relocate building south out of High-Risk
	Floodplain
	• <i>N/A</i>

The Commission found that the proposed work does not meet the criteria and standards in Chapter 14, <u>Article IV</u> of the Fort Collins Municipal Code. Upon amending this report on December 10, 2020, staff noted improvements on the project, specifically retention of the windows. While the loss of the historic addition on the rear and potential loss of minor landscape features does not meet the Standards, the overall project now appears to, and staff has adjusted the report to reflect that.

Based on the degree of alterations it is expected that the property will remain contributing to the district. However, any further alterations, such as replacement of siding, removal of porch posts, or further additions, would likely render the property non-contributing to the Laurel School Historic District and ineligible for potential City Landmark listing. That would also prohibit current and future owners from leveraging multiple financial incentives for historic preservation.

Notice of the completion of this report has been forwarded to building and zoning staff to facilitate the processing of any permits that are needed for the work. Please note that all ensuing work must conform to the approved plans. Any non-conforming alterations are subject to stop-work orders, denial of Certificate of Occupancy, and restoration requirements and penalties.

If you have any questions regarding the Commission's report or staff's amendments to that report included in this document, or if we may be of any assistance, please do not hesitate to contact our office at preservation@fcgov.com or 970-416-4250.

Sincerely,

Jim Bertolini Historic Preservation Planner



Planning, Development & Transportation Community Development & Neighborhood Services 281 North College Avenue P.O. Box 580 Fort Collins, CO 80522.0580

Plan of Protection for Historic Properties

Project Title: Naffziger Residence

Full Property Address: 600 Matthews Street, Fort Collins, 80524

Form Prepared by: Barry Schram

1.0 Introduction

1.1 Description of project location:

The Project is located at 600 Matthews Street, Fort Collins, Colorado, corner of Myrtle & Matthews Streets.

1.2 General description of work to be performed, including which firm(s) will be doing the work: The current home will be deconstructed from its current foundation, picked up and moved approximately 11' to the south to remove it from the high-risk floodplain, where a new foundation will be constructed and the structure will be placed / lowered onto the new foundation.

> Firms <u>Architect</u> VFLA – Taylor Meyer 419 Canyon Ave. #200, Fort Collins, CO 80521 970-224-1191 <u>General Contractor</u> Lamar Valley Craftsman – Barry Schram 2620 Brush Creek Drive, Fort Collins, CO 80528 970-690-8526

1.3 Building(s) or portion(s) of designated and eligible buildings within the area of adjacency that will be affected:

Only the primary building will be affected, as the existing garage is not be changed.

Is building adjacent to other buildings or structures, on or off site, and if so, how close?:

The building to the east neighboring this property is a single-family residence, that is approximately 5' from the property line. The building to the south is approximately 15' from the property line, which is a two-story commercial building. The relocation of the proposed residence will be approximately 35' from the property line to both the south and east property lines.

1.5 Are any of these other buildings or structures 50 years old or older (which ones, and what are their dates of construction, if known):

The existing garage on the property is likely early 1900's, and the buildings of the neighboring properties is unknown.

2.0 Scope of Work

Describe the work, and how it will affect any historic building(s) (both on the subject property and on adjacent properties, if applicable). Provide descriptions on each of the following, as applicable:

2.1 Demolition:

The only portion of the existing structure that will be removed is the current east side porch, which will be rebuilt to incorporate it into the main level floor to better utilize the space. Currently the porch is stepped down, and not integrated fully with the main floor plan. All other portions of the structure will remain.

2.2 Site preparation:

The existing stone pavers that makeup the walkway from the east side porch and connects the garage, house and Myrtle Street sidewalk will be saved and repurposed with the new landscaping at the conclusion of the project. The rest of the site will be blocked off with orange construction fencing for the duration of the project. Appropriate site safety signage will be installed at both the Matthews Street side and the Myrtle Street side.

The existing garage will be protected via plywood at the exterior walls, as will most of the main level windows on the main house.

The existing concrete driveway tracks will be difficult to maintain. The northern most track and some of the middle track will be in the excavation over-dig required per OSHA regulations. The southern most track will be protected via plywood and/or mats.

2.3 Excavation:

Soils testing has been performed by CDS Engineering out of Loveland, and the results show well compacted soils which will not require any additional shoring beyond typical excavation practices. The basement will be excavated an additional seven feet beyond the existing foundation depth to allow for a new basement.

2.4 Utilities:

Existing water service and sewer service will be reused. Gas line will be upgraded per Xcel Energy requirements. Electric service will be upgraded to current standards per City of Fort Collins Light & Power Department.

2.5 New foundation:

The new foundation will create a basement under the home, be 9' tall and reinforced concrete with two egress windows.

2.6 New construction:

The existing structure will be kept as is except for the removal and rebuilding of the east porch, as depicted in the VFLA plan set. The existing windows will also be rebuilt / repaired in order to make them operational and more energy efficient / air sealed.

2.7 Parking lot:

N/A

2.8 Driveways/alleyways:

Off street parking will be accomplished via the existing garage accessed via the Matthews Street entrance. There is no alley connected to the site.

2.9 Landscaping:

The established mature trees will be preserved in all the yards, and landscaping will be updated once the project is complete.

2.10 Drainage:

An upgraded drainage plan has been / will be submitted to City Fort Collins Planning with the required construction documents at permit application.

2.11 Other:

None.

3.0 Coordination of Project Activities

- 3.1 Name of person or persons responsible for overseeing the demolition and/or construction activities: Barry Schram, owner of Lamar Valley Craftsman
- 3.2 Will they be on site when that work is occurring? Yes

- 3.3 If not, how may they be contacted if needed when that work is underway? *Barry Schram @ 690-8526*
- 3.4 What specific coordination practices will be used to coordinate work activities? As Project Manager, Barry Schram will coordinate all the needed requirements with the house moving sub-contractor prior to and during this phase of the project.

4.0 Deconstruction, Salvaging & Recycling Materials

4.1 Which historic materials will be deconstructed and salvaged?

The existing doug-fir hardwood flooring will be kept in its current state, existing windows will be rebuilt, existing casework in the home will be kept as is, light fixtures will be repurposed in the home, concrete from existing slab will be recycled at City of Fort Collins facility, existing pavers / flagstones currently used as exterior walkways will be reused in the new landscaping.

4.2 Which historic materials will not be salvaged, and how will they be disposed of? N/A

5.0 Protection of Existing Historic Property

How will you ensure that historic buildings, structures, and surface features will not be damaged during work? What means will be used to protect them?

- 5.1 Site Conservation trees will be protected with orange boundary fence
- 5.2 Demolition of Building East side porch which will be removed & re-built once the house is moved onto its new foundation. The surface area / siding around this area will be kept in its current state, and rebuilt as needed make the new construction appear as it had been part of the original construction.
- 5.3 Foundation Stability existing foundation will be removed, and a new one placed. It will be the job of the house moving company to stabilize the house and remove the existing stone / cmu block foundation.
- 5.4 Structural Existing structure has been evaluated via Structural Elements Design / Jeremy Tuck and submitted to building department as part of the permit application process and will be stabilized / upgraded per building department requirements once the house is moved.
- 5.5 New Construction east side porch will be re-built per plan set details and protected as with any new project.
- 5.6 Historic Openings & Materials these will be protected via plywood prior to the move which will also help insure the property is vandalized once it is moved on the site.
- 5.7 New Openings N/A
- 5.8 Floor Framing see 5.4
- 5.9 Roof Structure and Roof Framing see 5.4

- 5.10 Structural Loads *see 5.4*
- 5.11 Supporting and Bracing of Existing Structure; Under-Pinning *This will be coordinated via Ryberg Construction and will rely on industry BMP to stabilize the house during this phase of construction.*
- 5.12 Excavation and Shoring of Existing Structure see 5.11
- 5.13 Site Cleanup Barry Schram will be responsible for ensuring the site is clean, which includes managing fugitive dust and cleaning up stray debris.

6.0 Documentation for Record

6.1 Does the project include measured drawings and/or photographs?

The project will use detailed Construction Documents created by an architect including structural design drawings. The documents have been / will be submitted to the building Department as part of the building permit process.

6.2 Where will these be stored?

Hard copy documents have been submitted to the Building Department and to Historical Preservation.

7.0 Archeology

How will you address archeological resources if they are likely to be present or if you should unexpectedly find them?


If discovered, the Fort Collins Museum of Discovery will be contacted immediately.


IMPERVIOUS SURFACE AREA CALCULATION
EXISTING IMPERVIOUS SURFACE AREAS: HOUSE 2082 SQ FT GARAGE 665 SQ FT SHED 156 SQ FT HARDSCAPE + 1135 SQ FT TOTAL 2903 SQ FT (24.2% OF LOT AREA) ADDITIONAL IMPERVIOUS SURFACE AREAS: HOUSE 222 SQ FT HARDSCAPE + 90 SQ FT TOTAL 312 SQ FT (2.6% OF LOT AREA) TOTAL SQ FT (2.6% OF LOT AREA)
CODE DATA
Codes: 2018 I.R.C. w/ LOCAL AMMENDMENTS 2018 I.F.C. 2018 I.E.C.C. ROOF MIN R-49 WALLS MIN R-20 BASEMENT WALLS MIN R-15 CONT. OR R-19 @ CAVITY WINDOW U-VALUE MAX .30 Address: 600 MATHEWS ST FORT COLLINS, CO 80524 Site Area: 0.28 ACRES (12,000 SF) Zone District: NCM DISTRICT Occupancy Classification: TYPE R-3 Construction Type: V-B Number of Stories: 2
Max Allowalbe Floor Area on Overall Lot: 4.8(D)(2)(a)3 35% of total lot area = (.35) x (12,000 sf) = 4200 sf Proposed Floor Area on Overall Lot: Existing - Garage 564 sf Existing - Main Level 1202 sf Existing - Upper Level 583 sf Addition - Main Level $+$ 313 sf TOTAL: = 2662 sf Max Allowalbe Floor Area on Rear Half of Lot: 4.8(D)(3) 33% of rear 50% of lot area = (.33) x (6,000 sf) = 1980 sf Proposed Floor Area on Rear Half of Lot: Existing - Garage 564 sf Existing - Garage 564 sf Existing - Main Level 438 sf Existing - Main Level 438 sf Existing - Upper Level 304 sf Addition - Main Level $+$ 313 sf TOTAL: = 2662 sf
TOTAL: = 1619 sf <u>FLOOR AREA ANALYSIS (SQ FT):</u>

FINISHED AREA	
Name	Area
ADDITION - BASEMENT	1356 SF
ADDITION - MAIN LEVEL	313 SF
EXISTING - MAIN LEVEL	1202 SF
EXISTING - UPPER LEVEL	583 SF
TOTAL:	3453 SF

IN THE CITY OF FORT COLLINS: ALL ROOFING PERMITS ARE REQUIRED TO COMPLETE A WASTE MANAGEMENT PLAN INCLUDING THE LOCATION & AMOUNT OF WASTE DISPOSED. <u>KEEP ALL LANDFILL &</u> <u>RECYCLING DISPOSAL TICKETS</u>. THE WASTE MANAGEMENT PLAN CAN BE FOUND AT fcgov.com/constructionrecycling

- FOR REMOVAL OF MUD AND DEBRIS AT THE END OF EACH DAY.
- INCLUDE THE COST OF REPAIR OR REPLACEMENT IN BASE BID.





FBS FULL BULDING SECTION FLOOR DRAIN FDN FOUNDATION

FIRE DEPARTMENT CONNECTION OFCI FIRE EXTINGUISHER OFF FIRE EXTINGUISHER CABINET FIRE HOSE CABINET OPG OPP OSB PART PARTITION FACE OF CONCRETE PC PRECAST PERIM FACE OF STUDS PERIMETER PLATE

OUTSIDE DIAMETER (DIM.) OVERFLOW DRAIN OVERFLOW DRAIN OWNER FURNISHED CONTRACTOR INSTALLED OFFICE OWNER FURNISHED AND INSTALLED OPPOSITE HAND OPENING OPPOSITE ORIENTED STAND BOARD

VOLUME VOL. VINYL WALL COVERING VWC WEST OR WOMEN WITH WATER TO CEMENT RATIO W/IN WITHIN W/O · WITHOUT WATER CLOSET WOOD WIDE ELANGE WF WIDE FLANGE WIN WINDOW

WATERPROOF(ING

WAINSCOT

WATER RESISTANT

WP

WR

\//\/F

DRAFTING SYMBOLS PROJECT DIRECTORY DRAWING TITLE SUSAN & DOUG NAFFZIGER OWNER FLOOR PLAN 600 MATHEWS ST FORT COLLINS, CO 80524 SCAL 1/4"=1'-0" (765) 748-5542 🖳 SCALE ARCHITECT VFLA, INC. DRAWING INDICATOR 419 CANYON AVENUE, SUITE 200 FORT COLLINS, CO 80521 DRAWING (970) 224-1191 NUMBER taylor@vfla.com A3. **A**3. CONTACT: TAYLOR MEYER JYP X LAMAR VALLEY CRAFTSMAN CONTRACTOR Modifier — 2620 BRUSH CREEK DRIVE SHEET NUMBER FORT COLLINS, CO 80528 PHONE: (970) 690-8526 **BUILDING SECTION** WALL SECTION OR DETAIL barry@lamarvalleycraftsman.com CONTACT: BARRY SCHRAM (101) **ELEVATION STRUCTURAL DESIGN** STRUCTURAL DOOR TAG PHONE: (307) 421-7868 (SEE DOOR SCHEDULE) tuck@elevation-sd.com CONTACT: JEREMY TUCK \langle A1 \rangle – SHEET NUMBER WINDOW OR FRAME TAG BART FUDGE INTERIOR DESIGNER **ELEVATION TAG** (SEE WINDOW OR FRAME TYPES) jb4barton@gmail.com W1 SYSTEM TAG (SEE SYSTEMS NOTES FOR DESCRIPTION) VICINITY MAP Α TOILET ACCESSORY TAG **COLUMN GRIDS** (SEE TOILET ACCESSORIES SCHEDULE) ROOM NAME 101 **ROOM TAG** AGNOLIA-< 1 >- CEILING HEIGHT ABOVE FLOOR SHEET NOTES CEILING TAG ON RCP (SEE LEGEND ON SHEET) — P-1 PARTITION TAG (SEE INTERIOR PARTITION TYPES) SITE 600 MATHE -MYRTLE-MATERIALS LEGEND ┍╴╤∕╼ ╚╴╴┛ BATT INSULATION XXXXXXX PLYWOOD OR OSB **BLOWN-IN INSULATION** STONE OR SYNTHETIC STONE BRICK **RIGID INSULATION** A -CONCRETE WALL OR PARTITION CONCRETE MASONRY _____ EARTH WOOD FINISH LUMBER GRAVEL \sim WOOD DIMENSION LUMBER GYPSUM BOARD [-<u>,</u>,,,,,,,] - - - -, MORTAR OR STUCCO WOOD BLOCKING

WELDED WIRE FABRI NOTE: SEE LEGENDS, DOOR SCHEDULE, ROOM FINISH SCHEDULE, AND CONSULTANTS' DRAWINGS FOR ADDITIONAL ABBREVIATIONS.

FEC.

FIN

FIXT

FI R

FO

FLUOR.

FOUND.

FIBERGLASS

FINISH(ED)

FLUORESCENT


FOUNDATION

FIXTURE

FACE OF


FLOOR


NAFFZIGER RESIDENCE



С	0	D	E	1	Γ)	A	Т	A	
des: <u>2018 I.R.C.</u> 2018 I.F.C.	<u>w/ LO(</u>	CAL A			<u>MEN[.] I.E.C</u>					
ROOF WALLS BASEM WINDO	S 1ENT V	VALLS ALUE	MIN S	NR-4 NR-2 MIN MAX	0 R-1	5 C(ЭNT	. OR	R-19)@
dress:			600 I				т			
			FOR						ŀ	
e Area:			0.28				000 \$	SF)		
ne District: cupancy Classifi	cation.		NCM TYPE							
nstruction Type:	cation.		V-B	_ 1.	U					
mber of Stories:			2							
					<u> </u>					
Max	Allowal 4 8(D	be Flo)(2)(a		rea o	n Ov	era	ll Lot			
	35%	of tota 5) x (1	al lot							
	= 420		2,00	0 31)						
Prop	oosed F	loor A	Area	on O	veral	l Lo	t:			
		ting - ting -			al		564 202			
	Exis	ting -	Uppe	er Le	vel		583	sf		
	Add	ition -			<u>el</u> L:					
			•				002	51		
Max	Allowal 4.8(D		oor A	rea o	n Re	ar F	lalt c	of Lot		
	33%	of rea			ot ar	ea				
	= (.33 = 198	3) x (6 30 sf	5,000	ST)						
Pror	bosed F	-loor A	Area	on R	ear ⊦	Ialf (of Lo	ot:		
1.0	Exis	ting -	Gara	ige			564	sf		
		ting - ting -								
	Add	ition -	Mair	l Lev	<u>el</u> L:	+	313	sf		
					L:	= 1	619	ST		
<u></u> <u>FL</u>	.00R	AR	EA	AN/	<u>ALY</u>	SIS	<u>s (s</u>	Q F	Τ):	
		۶IN	VISH	HED) AF	REA	4			
		Na	me		. • .			Ar	ea	
ADD	TION	l - B/	ASE	ME	NT			135	56 S	SF
ADD	TION	I - M	AIN	LE'	VEL	.		3′	13 S	SF
EXIS	TING	- M	AIN	LE	/EL			120)2 S	SF
EXIS	TING	- U	PPE	RL	EVI	ΞL		58	33 S	SF
				T	ΟΤΑ	۱L:		345	53 S	ŝF
										_
					. •					
					· .					

IN THE CITY OF FORT COLLINS: ALL ROOFING PERMITS ARE REQUIRED TO COMPLETE A WASTE MANAGEMENT PLAN INCLUDING THE LOCATION & AMOUNT OF WASTE DISPOSED. KEEP ALL LANDFILL & <u>RECYCLING DISPOSAL TICKETS.</u> THE WASTE MANAGEMENT PLAN CAN BE FOUND AT fcgov.com/constructionrecycling








GENERAL DEMOLITION NOTES

- 1. THE CONTRACTOR SHALL COORDINATE AND IMPLEMENT ALL SAFETY MEASURES REQUESTED AND REQUIRED BY THE LOCAL FIRE MARSHALL, HEALTH DEPARTMENT, BUILDING OFFICIALS AND OTHER GOVERNING AGENCIES.
- 2. THE CONTRACTOR SHALL COORDINATE THE SALVAGE OF EXISTING MATERIAL AND EQUIPMENT WITH THE OWNER. THE OWNER RETAINS SALVAGE RIGHTS TO MATERIALS AND EQUIPMENT REMOVED FROM THE BUILDING AS PART OF THE PROJECT.
- 3. THE CONTRACTOR SHALL REPAIR AND/OR REPLACE ALL EQUIPMENT WHICH IS TO REMAIN IF DAMAGED BY CONSTRUCTION ACTIVITES.
- 4. REMOVE EXISTING EXTERIOR LIGHTING EXCEPT AS SHOWN TO REMAIN. RE-USE CONDUIT UNLESS OTHERWISE REQUIRED BY NEW CONSTRUCTION.
- 5. THE CONTRACTOR SHALL MAINTAIN THE SECURITY OF THE BUILDING THROUGHOUT THE ENTIRE CONSTRUCTION SCHEDULE.
- 6. ON SITE SALE AND/OR DISPOSAL OF AND/OR BURNING OF DEMOLISHED ITEMS IS NOT PERMITTED. 7. REMOVE ADHESIVE FROM FLOOR SURFACES WHERE GLUE APPLIED CARPETING HAS BEEN REMOVED AND WHERE VCT HAS BEEN REMOVED.
- 8. THE CONTRACTOR SHALL KEEP ALL EXIT WAYS FREE OF STORED MATERIALS AND CONSTRUCTION DEBRIS AT ALL TIMES IN ORDER TO GIVE NEIGHBOORS CLEAR ACCESS TO EXIT WAYS.
- 9. DISRUPTION OF UTILITIES TO THE EXISTING BUILDING SHALL BE COORDINATED WITH THE OWNER AT LEAST 48 HOURS PRIOR TO THE PLANNED DISRUPTION.


`+`__`__`__`__`__`__`__`__`__`__`

 $V/L \rightarrow - - - - - - - - - - - - - +$

┖┲╋┽╅╋╋









- REVIEW ALL OF THE DRAWINGS, INCLUDING ARCHITECTURAL, FOR WORK UNDER THEIR RESPECTIVE CONTRACTS. ROOF PLANS AND REFLECTED CEILING PLANS DESCRIBE MECHANICAL AND ELECTRICAL WORK AS DO OTHER DRAWINGS. NO EXTRAS WILL BE ALLOWED FOR WORK SHOWN IN ANY PART OF THESE DRAWINGS, OR DESCRIBED IN ANY PART OF THE SPECIFICATIONS.
- DIMENSION IS TO FINAL FINISH.

- BATHROOMS, BEDROOMS, AND LAUNDRY ROOMS






NAFFZIGER RESIDENCE
600 MATHEWS STREET FORT COLLINS, CO 80524
<section-header><section-header><section-header><section-header><section-header><text></text></section-header></section-header></section-header></section-header></section-header>
ELEVATIONS STRUCTURAL DESIGN PHONE: (307) 421-7868 tuck@elevation-sd.com CONTACT: JEREMY TUCK
CONSTRUCTION SET 11-13-2020 SHEET ISSUANCES DESCRIPTION DATE
REVISIONS No. Description Date
DRAWN BY: TM CHECKED BY: TM SEAL:
COLOR DAVIO LICE 10 ON DAVIO LICE 10 11-13-2020 2 404235 5 CHITECI
COPYRIGHT: 11/13/2020 5:25:00 PM VAUGHT FRYE LARSON ARONSON ARCHITECTURE + INTERIORS, INC. THIS DRAWING MAY NOT BE PHOTOGRAPHED, SCANNED, TRACED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF VFLA.
LOWER FLOOR PLAN
DRAWING NUMBER:

PROJECT NUMBER:

2019-14



GENERAL NOTES


- DO NOT SCALE DRAWINGS. <u>FIELD VERIFY ALL DIMENSIONS</u>. NOTIFY ARCHITECT IMMEDIATELY WHEN DISCREPANCIES ARE DISCOVERED.
- IT IS THE RESPONSIBILITY OF THE MECHANICAL AND ELECTRICAL SUBCONTRACTORS TO REVIEW ALL OF THE DRAWINGS, INCLUDING ARCHITECTURAL, FOR WORK UNDER THEIR RESPECTIVE CONTRACTS. ROOF PLANS AND REFLECTED CEILING PLANS DESCRIBE MECHANICAL AND ELECTRICAL WORK AS DO OTHER DRAWINGS. NO EXTRAS WILL BE ALLOWED FOR WORK SHOWN IN ANY PART OF THESE DRAWINGS, OR DESCRIBED IN ANY PART OF THE SPECIFICATIONS.
- DIMENSIONS ARE FROM FACE OF STUD, FACE OF MASONRY, OR FACE OF CONCRETE AND TO GRID LINES UNLESS NOTED OTHERWISE. WHERE DIMENSION IS NOTED "CLEAR", DIMENSION IS TO FINAL FINISH.
- VERIFY WINDOW LOCATIONS AND SIZING ON EXTERIOR ELEVATIONS AND FLOOR PLANS.
- PROVIDE BLOCKING WHERE REQUIRED.

3' - 0"

FENCE


7' - 8"

BATHROOMS, BEDROOMS, AND LAUNDRY ROOMS




2019-14

PROJECT NUMBER:










NAFFZIGER

RESIDENCE

GENERAL	NOTES
---------	-------

600 MATHEWS STREET FORT COLLINS, CO 80524
<section-header><section-header><section-header><section-header><text></text></section-header></section-header></section-header></section-header>
ELEVATION STRUCTURAL DESIGN PHONE: (307) 421-7868 tuck@elevation-sd.com CONTACT: JEREMY TUCK
CONSTRUCTION SET 11-13-2020 Sheet issuances
DESCRIPTION DATE
REVISIONS No. Description Date
DRAWN BY: TM
CHECKED BY: TM
SEAL:
COPYRIGHT: 11/13/2020 5:25:02 PM VAUGHT FRYE LARSON ARONSON ARCHITECTURE + INTERIORS, INC. THIS DRAWING MAY NOT BE PHOTOGRAPHED, SCANNED, TRACED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF VFLA.
UPPER FLOOR PLAN & LOWER ROOF PLAN
DRAWING NUMBER:






GENERAL CEILING NOTES

- CEILING HEIGHTS AS NOTED ON THIS PLAN, REFERNECE INTERIOR ELEVATIONS FOR GYP. BOARD SOFFIT HEIGHTS. ALL CEILING HEIGHTS TO B.O. STRUCTURE UNLESS NOTED OTHERWISE. COORDINATE ALL MECHANICAL, ELECTRICAL, AND FIRE SUPPRESSION SYSTEMS THAT INTERFACE WITHIN CEILING.
- IT IS THE RESPONSIBILITY OF THE MECHANICAL AND ELECTRICAL SUBCONTRACTORS TO REVIEW ALL OF THE DRAWINGS, INCLUDING ARCHITECTURAL, FOR WORK UNDER THEIR RESPECTIVE CONTRACTS. ROOF PLANS AND REFLECTED CEILING PLANS DESCRIBE MECHANICAL AND ELECTRICAL WORK AS DO OTHER DRAWINGS. NO EXTRAS WILL BE ALLOWED FOR WORK SHOWN IN ANY PART OF THESE DRAWINGS, OR DESCRIBED IN ANY PART OF THE SPECIFICATIONS.
- PROVIDE A MINIMUM OF R-13 INSULATION BETWEEN FLOOR JOIST ABOVE LIVING UNITS.
- ALL GYP. BOARD TERMINATION AT MASONARY WALLS SHALL HAVE A 1/4" J-MOLD REVEAL.
- ALL SOFFITED CONCEALED SPACES TO BE CONSTRUCTED OF LIGHT GAUGE MTL STUDS AND GYP BOARD.

GENERAL NOTES


- DO NOT SCALE DRAWINGS. FIELD VERIFY ALL DIMENSIONS. NOTIFY ARCHITECT IMMEDIATELY WHEN DISCREPANCIES ARE DISCOVERED.
- IT IS THE RESPONSIBILITY OF THE MECHANICAL AND ELECTRICAL SUBCONTRACTORS TO REVIEW ALL OF THE DRAWINGS, INCLUDING ARCHITECTURAL, FOR WORK UNDER THEIR RESPECTIVE CONTRACTS. ROOF PLANS AND REFLECTED CEILING PLANS DESCRIBE MECHANICAL AND ELECTRICAL WORK AS DO OTHER DRAWINGS. NO EXTRAS WILL BE ALLOWED FOR WORK SHOWN IN ANY PART OF THESE DRAWINGS, OR DESCRIBED IN ANY PART OF THE SPECIFICATIONS.
- DIMENSIONS ARE FROM FACE OF STUD, FACE OF MASONRY, OR FACE OF CONCRETE AND TO GRID LINES UNLESS NOTED OTHERWISE. WHERE DIMENSION IS NOTED "CLEAR", DIMENSION IS TO FINAL FINISH.
- VERIFY WINDOW LOCATIONS AND SIZING ON EXTERIOR ELEVATIONS AND FLOOR PLANS.
- PROVIDE BLOCKING WHERE REQUIRED.
- PROVIDE R-13 ACOUTIC BATT INSULATION AT INTERIOR PARTITIONS SURROUNDING ALL BATHROOMS, BEDROOMS, AND LAUNDRY ROOMS



PROJECT NUMBER:

2019-14
























	ALIGN WINDOW HEAD WITH NEARBY WINDOW "B" ON WEST WALL OF MASTER CLOSET	RDRA
G:\2019\19-14 Naffziger Residence\5 Revit\Naffziger Residence Remodel - REVISED PLAN.rvt	$1/2^{"}$	
G:\2019\19-14 Naffziger Residence\5 Revi		
11/13/2020 5:25:20 PM	1 PROPOSED NORTH 1/4" = 1'-0"	<u>I E</u>

















GENERAL NOTES


- DO NOT SCALE DRAWINGS. <u>FIELD VERIF</u> IMMEDIATELY WHEN DISCREPANCIES AR
- IT IS THE RESPONSIBILITY OF THE MECHAI REVIEW ALL OF THE DRAWINGS, INCLUDIN RESPECTIVE CONTRACTS. ROOF PLANS A MECHANICAL AND ELECTRICAL WORK AS ALLOWED FOR WORK SHOWN IN ANY PAR PART OF THE SPECIFICATIONS.
- DIMENSIONS ARE FROM FACE OF STUD, I AND TO GRID LINES UNLESS NOTED OTHI DIMENSION IS TO FINAL FINISH.
- VERIFY WINDOW LOCATIONS AND SIZING PROVIDE BLOCKING WHERE REQUIRED.
- PROVIDE R-13 ACOUTIC BATT INSULATION BATHROOMS, BEDROOMS, AND LAUNDRY







				PROJECT NUMBER: 20"	19-14
				NAFFZ	
IFY ALL DIMENSIONS. NOTIFY ARCHITECT ARE DISCOVERED. HANICAL AND ELECTRICAL SUBCONTRACTORS TO					
DING ARCHITECTURAL, FOR WORK UNDER THEIR IS AND REFLECTED CEILING PLANS DESCRIBE AS DO OTHER DRAWINGS. NO EXTRAS WILL BE				600 MATHEW FORT COLI 8052	LINS, CO
PART OF THESE DRAWINGS, OR DESCRIBED IN ANY					
), FACE OF MASONRY, OR FACE OF CONCRETE HERWISE. WHERE DIMENSION IS NOTED "CLEAR",					
IG ON EXTERIOR ELEVATIONS AND FLOOR PLANS.					
). ON AT INTERIOR PARTITIONS SURROUNDING ALL				VAUGHT FRYE LA	
RY ROOMS				Strength in design. Stre	angth in partnership
				Strength in c	ommunity.
				419 Canyon Ave Suite 200, Fort Col 108 East Lincolnway, Cheyenne, www.VFL	WY 82001 307.635.5710 A.com
				IN ASSOCIATION WITH:	
				ELEVA STRUCTURA	
				PHONE: (307) 421-7 tuck@elevation-sd.co	7868 om
				CONTACT: JEREM	TUCK
<u> </u>				CONSTRUCTION	
<u>ل</u> ا				SHEET ISSUANCES	
				DESCRIPTION	DATE
				REVISIONS	
				No. Description	Date
		M	AIN_LEVEL 100' - 0"	DRAWN BY: TM CHECKED BY: TM	
		1' - 10 1/4" ; RISERS @ 7/16" EACH	100 - 0	SEAL:	
		1' - ' 3 RIS 7 7/16			m.
			98' - 1 3/4" 🔍	COLOR DAI	LICENSCO
YP.				₩ 11-13- ₩ 404:	2020 35 5
	a 4 	EACH		TAC	TECT
	4 · · · · · · · · · · · · · · · · · · ·	1/4" 7 7/16"			ALLINGS .
		7' - 5 RISERS @			
		12 RIS		COPYRIGHT: 11/13/2020 5:25:22 PM VAUGHT FRYE LARSON ARONSON AF THIS DRAWING MAY NOT BE PHOTOG COPIED IN ANY MANNER WITHOUT THI	RAPHED, SCANNED, TRACED OR
	4				= WRITTEN PERMISSION OF VELA
		LOV	/ER_LEVEL 90' - 8 1/2"	STAIR SE	CTIONS
4' - 0 3/4" \CH					
				DRAWING NUMBER:	
				A6	: 1
					/. 1








1/2" = 1'-0"






PROJECT NUMBER:	2019-14
ΝΔΙ	FZIGER
	SIDENCE
NEG	DIDENCE
	IATHEWS STREET
FO	RT COLLINS, CO 80524
\ <i>/</i> F	— 1 A
	RYE LARSON ARONSON CTURE + INTERIORS
	gn. Strength in partnership. gth in community.
419 Canyon Ave Suite 108 East Lincolnwa	200, Fort Collins, CO 80521 970.224.1191 y, Cheyenne, WY 82001 307.635.5710
	www.VFLA.com
IN ASSOCIATION WITH:	
EL E	VATION
	TURAL DESIGN
tuck@eleva	07) 421-7868 tion-sd.com
CONTACT:	JEREMY TUCK
CONSTRUC	TION SET 11-13-2020
SHEET ISSUANCES	
	TION SET 11-13-2020 Date
SHEET ISSUANCES	
SHEET ISSUANCES	
SHEET ISSUANCES	
SHEET ISSUANCES DESCRIPTION	<u>DATE</u>
SHEET ISSUANCES DESCRIPTION	
SHEET ISSUANCES DESCRIPTION	<u>DATE</u>
SHEET ISSUANCES DESCRIPTION	<u>DATE</u>
SHEET ISSUANCES DESCRIPTION	DATE
SHEET ISSUANCES DESCRIPTION	<u>DATE</u>
SHEET ISSUANCES DESCRIPTION	DATE
SHEET ISSUANCES DESCRIPTION	DATE
SHEET ISSUANCES DESCRIPTION	DATE
SHEET ISSUANCES DESCRIPTION	
SHEET ISSUANCES DESCRIPTION	DATE
SHEET ISSUANCES DESCRIPTION Image: Comparison of the comp	DATE
SHEET ISSUANCES DESCRIPTION Image: Comparison of the comp	DATE
SHEET ISSUANCES DESCRIPTION	DATE


A7.1

11/13/2020 5:25:23 PM

G:\2019\19-14 Naffziger Residence\5 Revit\Naffziger Residence Remodel - REVISED PLAN.n

					DOOR SCHEDULE
Door	Double Door	DO SIZ		DOOR PANEL	
No.	Indicator	W×	(H	Туре	Comments
001		30"	80"	В	
002		24"	80"	B	
003		30"	80"	B	
004		30"	80"	B	
005		36"	80"	D	
006		36"	80"	В	
007		36"	80"	D	
008		24"	80"	В	
009		30"	80"	В	
010		36"	80"	В	
101		36"	80"	F	CUSTOM ENTRY DOOR - STYLE TBD BY OWNER
102		32"	96"	D	
103		30"	96"	D	
104		30"	96"	D	
105		30"	96"	D	
106		30"	80"	D	
107		36"	80"		ENTRY DOOR w/ SIDELITE
108	(2)		80"	E	
109		28"	96"	Α	
110		30"	80"		ENTRY DOOR
201		30"	80"	C	
202		30"	80"	D	
203		30"	60"		DOOR HEIGHT TO BE VERIFIED IN FIELD
204		30"	52"		EXISTING DOOR TO REMAIN (VIF), REFINISH
205		30"	52"		EXISTING DOOR TO REMAIN (VIF), REFINISH
206		30"	52"		EXISTING DOOR TO REMAIN (VIF), REFINISH
207		30"	78"		EXISTING DOOR TO REMAIN (VIF), REFINISH
208		30"	78"		EXISTING DOOR TO REMAIN (VIF), REFINISH
209		30"	78"	Α	EXISTING DOOR TO REMAIN (VIF), REFINISH







DOOR LEGEND 1/2" = 1'-0"

*<u>NOTE</u>: REFER TO FLOOR PLANS & EXTERIOR E

	PROJECT NUMBER: 2019-14
	NAFFZIGER RESIDENCE
	600 MATHEWS STREET FORT COLLINS, CO 80524
	VAUGHT FRYE LARSON ARONSON ARCHITECTURE + INTERIORS Strength in design. Strength in partnership.
	Strength in community. 419 Canyon Ave Suite 200, Fort Collins, CO 80521 970.224.1191 108 East Lincolnway, Cheyenne, WY 82001 307.635.5710 www.VFLA.com
	ELEVATION STRUCTURAL DESIGN PHONE: (307) 421-7868 tuck@elevation-sd.com CONTACT: JEREMY TUCK
RE: SCHEDULE	CONSTRUCTION SET 11-13-2020 Sheet issuances
RE: SCHEDULE	DESCRIPTION DATE
TYPE H NEW SWING SIDE-ENTRY DOOR HALF LITE WITH SIDE LITE	
	DRAWN BY: TM CHECKED BY: TM SEAL:
	CONTRADO LICENTO CONTRADO LICENTO IN 11-13-2020 TACHITECI CHITECI
	COPYRIGHT: 11/13/2020 5:25:23 PM VAUGHT FRYE LARSON ARONSON ARCHITECTURE + INTERIORS, INC. THIS DRAWING MAY NOT BE PHOTOGRAPHED, SCANNED, TRACED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF VFLA.
RE: SCHEDULE RE: SCHEDULE TYPE E NEW DOUBLE SWING DOOR	DOORS SCHEDULE & DETAILS
IOR ELEVATIONS FOR DOOR SWING OR POCKET DIRECTION	DRAWING NUMBER:








	PROJECT NUMBER: 2019-14
	<section-header><section-header><text><text><text><text><text><text><text><text></text></text></text></text></text></text></text></text></section-header></section-header>
	CONSTRUCTION SET 11-13-2020 SHEET ISSUANCES DESCRIPTION DATE
VET BAR 17 KFAST OM METER METER	CHECKED BY: TM SEAL:
	COPYRIGHT: 11/13/2020 5:25:24 PM VAUGHT FRYE LARSON ARONSON ARCHITECTURE + INTERIORS, INC. THIS DRAWING MAY NOT BE PHOTOGRAPHED, SCANNED, TRACED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF VFLA.
	DRAWING NUMBER:






































D. ACI 332-14 'RESIDENTIAL CODE REQUIREMENTS FOR STRUCTURAL CONCRETE'

E. NDS 2018 EDITION 'NATIONAL DESIGN SPECIFICATION FOR WOOD CONSTRUCTION'

C. ASCE/SEI 7-16 'MINIMUM DESIGN LOADS FOR BUILDINGS AND OTHER

GENERAL

- SHOWN IN TABLE R602.3(1) OF THE 2018 IRC. SUCH THAT THEY CAN BE INSTALLED IN A DRY SERVICE CONDTION WITH A
- MOISTURE CONTENT ≤ 19%.
- SHEATHING WITHOUT PRIOR WRITTEN CONSENT FROM THE ENGINEER.
- A. ALL FRAMING LUMBER AND MATERIALS SHALL BE IN ACCORDANCE WITH THE WITHIN THE PLANS AND DETAILS.
- DIMENSION LUMBER (2" 4" THICK) = HEM-FIR (HF) #2 OR BETTER TIMBERS (5" THICK & GREATER) C. FABRICATED LUMBER:
- WOOD I-JOISTS = RE: PLAN LAMINATED VENEER LUMBER (LVL) = f'b = 2800 PSI (MIN), E = 2.0 (MIN)
- IN DOC PS 1 & DOC PS 2).
- OF DESIGN. ALL METAL CONNECTORS CALLED OUT IN PLANS & DETAILS ARE MANUFACTURED BY SIMPSON STRONG-TIE. THE MANUFACTURER'S WRITTEN INSTRUCTIONS. FILL ALL NAIL AND/OR BOLT
- HOLES, INCLUDING OPTIONAL LOCATIONS FOR UPLIFT FORCES.
- A. DEAD LOADS FLOOR = 20 PSF ROOF = 20 PSF B. LIVE LOADS = 40 PSF FLOOR ROOF = 20 PSF C. SNOW LOADS GROUND SNOW (Pg) = 30 PSF DESIGN FLAT ROOF SNOW (Pf) = 30 PSF (UNREDUCABLE) 3. WIND AND SEISMIC DESIGN CRITERIA A. WIND LOAD DESIGN CRITERIA: = 125 MPH (BASED ON FRONT BASIC ULTIMATE WIND SPEED RANGE WIND CONTOUR MAP) BASIC NOMINAL WIND SPEED = 97 MPH EXPOSURE CATEGORY = B B. SEISMIC LOAD DESIGN CRITERIA: SEISMIC DESIGN CATEGORY = B SITE CLASS = D (ASSUMED) 4. FOUNDATION DESIGN CRITERIA A. FOUNDATION DESIGN IS BASED ON THE SOILS REPORT PROVIDED BY CDS ENGINEERING (PROJECT NO. 20-0425) DATED JULY 23, 2020. ALLOWABLE BEARING PRESSURE = 1500 PSF MINIMUM DEAD LOAD PRESSURE = 500 PSF FROST DEPTH = 30 IN LATERAL (AT-REST) PRESSURE = 55 PCF 5. BRACED WALL PANELS
- A. BRACED WALL PANEL DESIGN IS BASED ON THE REQUIREMENTS OF SECTION 602.10 OF THE 2018 IRC.
- B. BRACED WALL PANEL TYPES AND LOCATIONS ARE SHOWN ON PLAN.

GENERAL NOTES & REQUIREMENTS

- 1. GENERAL A. THE STRUCTURE IS DESIGNED TO FUNCTION AS A UNIT UPON COMPLETION. NOTHING SHOWN IN STRUCTURAL DRAWINGS SHALL BE INFERRED TO ALLEVIATE THE NEED FOR TEMPORARY BRACING, SHORING, ETC... WHICH MAY ARISE FROM THE CONTRACTOR'S MEANS, METHODS AND/OR SEQUENCING.
- B. DO NOT SCALE DRAWINGS. 2. FOUNDATION NOTES

1. CODES AND STANDARDS

STRUCTURES'

2. DEAD, LIVE AND SNOW LOADS

A. INTERNATIONAL RESIDENTIAL CODE (IRC) 2018

B. INTERNATIONAL BUILDING CODE (IBC) 2018

- A. EXISTING SITE CONDITIONS
- ALL UTILITIES SHALL BE LOCATED PRIOR TO EXCAVATION. IF UTILITES ARE DISCOVERED WITHIN THE BUILDING PAD FOOTPRINT, CONTACT ARCHITECT & ENGINEER PRIOR TO PROCEEDING WITH CONSTRUCTION. 2. ALL EXISTING SOILS CONTAINING VEGETATION, ORGANIC MATTER OR OTHER
- FORIEGN DEBRIS SHALL BE REMOVED FROM THE BUILDING PAD FOOTPRINT. B. SUBGRADE PREPERATION 1. ALL FOOTINGS & FOUNDATIONS SHALL BEAR ON PROPERLY COMPACTED
- STRUCTURAL FILL. REFER TO THE PROJECT'S GEOTECHNICAL REPORT FOR STRUCTURAL FILL & COMPACTION REQUIREMENTS. 2. COMPACT ALL SOFT SPOTS IN FOOTING EXCAVATIONS
- 3. ALL FOUNDATION EXCAVATIONS SHALL BE FREE OF LOOSE MATERIAL PRIOR TO FORMING OR PLACING CONCRETE.
- C. OPEN HOLE INSPECTIONS 1. OPEN HOLE INSPECTIONS ARE NOT PROVIDED BY ELEVATION STRUCTURAL DESIGN AND ARE THE RESPONSIBILITY OF THE CONTRACTOR OR OWNER. 2. A GEOTECHNICAL ENGINEERING, LICENSED IN THE STATE OF COLORADO, SHALL BE OBTAINED TO PROVIDE THE OPEN HOLE INSPECTION AND VERIFY THAT THE ON-SITE SOIL CONDITIONS MEET OR EXCEED FOUNDATION DESIGN CRITERIA SHOWN ABOVE. IF THE ON-SITE SOIL CONDITIONS DO NOT MEET OR EXCEED THE FOUNDATION DESIGN CRITERIA, CONTACT THE ARCHITECT & ENGINEER PRIOR TO PROCEEDING WITH CONSTRUCTION.
- D. PROVIDE FOUNDATION DRAINS MEETING THE REQUIREMENTS OF THE GEOTECHNICAL REPORT AND THE 2018 IBC.
- 3. EXISTING CONDITIONS
- A. THE CONTRACTOR SHALL FIELD VERIFY AND COORDINATE ALL EXISTING CONDITIONS PRIOR TO THE PREPARATION OF SHOP DRAWINGS AND PRIOR TO PROCEEDING WITH THE WORK.
- B. STRUCTURAL DOCUMENTS HAVE BEEN PREPARED WITH THE USE OF EXISTING DRAWINGS AVAILABLE DURING DESIGN AND THROUGH VISUAL SITE OBSERVATIONS WHEN ACCESSIBLE. DURING CONSTRUCTION, THE CONTRACTOR MAY DISCOVER UNFORESEEN EXISTING CONDITIONS WHICH COULD BE IN CONFLICT WITH THE CONTRACT DOCUMENTS
- C. IN THE EVENT OF SUCH DISCOVERIES, THE CONTRACTOR SHALL SUBMIT A DETAILED, DIMENSIONED SKETCH SHOWING ALL EXISTING STRUCTURE AND OTHER RELEVANT MATERIALS AND CONDITIONS TO THE ARCHITECT AND EOR PRIOR TO PROCEEDING WITH THE WORK.
- D. THE CONTRACTOR SHALL TAKE CARE TO NOT DAMAGE, SCUFF, SCAR OR MAR EXISTING SURFACES TO REMAIN IN THE FINAL CONDITION. ALL DAMAGED MATERIALS SHALL BE REPAIRED OR REPLACED AT THE CONTRACTOR'S EXPENSE.

STRUCTURAL STEEL NOTES & SPECIFICATIONS

1. GENERAL


- A. ALL WORK SHALL CONFORM WITH THE AISC CODE OF STANDARD PRACTICE, LATEST EDITION.
- B. FABRICATOR QUALIFICATIONS: a. THE FABRICATOR SHALL BE A COMPANY SPECIALIZING IN THIS TYPE OF WORK WITH (5) YEARS DOCUMENTED EXPERIENCE ON PROJECTS OF SIMILAR SIZE & COMPLEXITY.
- 2. STRUCTURAL STEEL MATERIALS
- A. ALL STRUCTURAL STEEL MATERIALS SHALL BE IN ACCORDANCE WITH THE REQUIREMENTS OUTLINED BELOW, UNLESS SPECIFICALLY NOTED OTHERWISE WITH THE PLANS & DETAILS.

В.	FRAMING MEMBERS:		
	WIDE FLANGE (W)	=	ASTM A992
	PLATE (PL)	=	ASTM A36
	ANGLE (L)	=	ASTM A36
С.	ADJUSTABLE STEEL COLUMNS:		
	ADJUSTABLE STEEL COLUMNS SHALL	BE	FABRICATED WITH ASTM A53, Gr. B
	PIPE MATERIAL OR BETTER.		
	 MINIMUM AXIAL CAPACITY 	=	P _{MIN} = 24,000 LBS
D.	CONNECTION MATERIALS:		


= ASTM A36

= E70XX


- = ASTM F1554, Gr. 55 (WELDABLE) ANCHOR RODS = ASTM A325
- BOLTS THREADED ROD WELDING ELECTRODES
- 3. STRUCTURAL STEEL CONNECTIONS
- A. ALL BOLTS SHOWN IN STRUCTURAL STEEL CONNECTIONS SHALL BE SNUG-TIGHT AS DEFINED BY THE 'SPECIFICATION FOR STRUCTURAL JOINTS USING HIGH STRENGTH BOLTS', RCSC SPECIFICATION SECTION 4.1. B. WELDERS SHALL HAVE, IN THEIR POSSESSION, CURRENT EVIDENCE PASSING THE
- APPROPRIATE A.W.S. QUALIFICATION TESTS. C. ALL GROOVE WELDS SHOWN SHALL BE COMPLETE JOINT PENETRATION (CJP)
- WELDS UNLESS SPECIFICALLY NOTED OTHERWISE IN THE PLANS & DETAILS. D. FIELD WELDING SYMBOLS INDICATE SUGGESTED CONSTRUCTION PROCEDURES.
- 4. STRUCTURAL STEEL FINISH A. ALL STRUCTURAL STEEL SHALL BE SURFACE PREPPED SUCH THAT IT IS FREE OF RUST, LOOSE MILL SCALE, DIRT AND OTHER DEBRIS IN ACCORDANCE WITH SSPC-SP2 OR SSPC-SP3.
- B. UNLESS OTHERWISE SPECIFIED WITHIN THE PLANS & DETAILS, THE FABRICATORS STANDARD SHOP PRIMER SHALL BE APPLIED TO ALL STRUCTURAL STEEL. C. EXPOSED STRUCTURAL STEEL BE SURFACE PREPPED, PRIMED AND PAINTED TO THE ARCHITECTS SATISFACTION.



1/4" = 1'-0"



(1)




EXISTING MAIN FLOOR SUPPORT FRAMING PLAN 1/4" = 1'-0"


- EXISTING CONDITIONS:
 A. THE EXISTING FLOOR JOIST LAYOUT SHOWN IS OUR UNDERSTANDING OF THE FRAMING SYSTEM. WE WERE UNABLE TO VERIFY ALL EXISTING FLOOR FRAMING, AND AS A RESULT, THE CONTRACTOR MAY DISCOVER FRAMING CONDITIONS WHICH DO NOT MATCH THE PLAN. B. CONTACT ENGINEER IF SIGNIFICANT DISCREPANCIES ARE
- DISCOVERED. C. DIMENSIONS SHOWS ON THIS PLAN SHALL BE FIELD VERIFED AND COORDINATED WITH EXISTING CONDTIONS
- PRIOR TO FABRICATION OF STRUCTURAL STEEL. 2. COLUMNS & BASEPLATES:
- A. FOR BASEPLATE TYPES, ANCHOR BOLT SIZES AND LOCATIONS, RE:
- 3. STEEL BEAMS:
- A. TOP OF STEEL ELEVATION SHALL BE SET SUCH THAT THE NAILER PLATE FLUSHES OUT WITH THE TYPICAL SILL PLATE.

MAIN FLOOR SUPPORT FRAMING PLAN KEYNOTES

(1) BEAM POCKET; RE: 9 / S2.0



NAFFZIGE RESIDENC	
600 MATHEWS ST. FORT COLLINS, CO 80524	
VAUGHT FRYE LARSON ARCHITECTURE + INT	
Strength in design. Strength in Strength in commun 419 Canyon Ave Suite 200, Fort Collins, CO 8052 108 East Lincolnway, Cheyenne, WY 82001 www.VFLA.com	ity. 1 970.224.1191
IN ASSOCIATION WITH:	
Project Status	
DESCRIPTION	DATE
CONSTRUCTION DRAWINGS STRUCTURAL CDS	07/30/20 11/13/20
REVISIONS	
No. Description	Date
DRAWN BY: JD, JT	
CHECKED BY: JT SEAL:	
50175 50175 50175 50175	
COPYRIGHT: 11/13/2020 1:48:37 PM VAUGHT FRYE LARSON ARONSON ARCHITECTUR THIS DRAWING MAY NOT BE PHOTOGRAPHED, SC COPIED IN ANY MANNER WITHOUT THE WRITTEN I	ANNED, TRACED O
EXISTING MAIN SUPPORT FRA PLAN	




FRAMING PLAN NOTES


1. WALLS:

- A. ALL EXTERIOR WALLS SHOWN IN PLAN ARE 2x6 HF#2 AT 16"OC, TYP UNO.
- B. PROVIDE TREATED SILL PLATE, TYP.C. PROVIDE 7/16" APA RATED WALL SHEATHING. NAIL TO WALL STUDS W/ 8d COMMONS: 6"OC AT EDGE & 12"OC IN FIELD, TYP UNO IN PLANS & DETAILS.
- 2. FLOORS:
- A. FOR FRAMING MEMBER SIZES & LOC(S), RE: PLAN.B. PROVIDE 3/4" APA RATED, T&G, FLOOR SHEATHING, TYP UNO. GLUE & NAIL TO SUPPORTING MEMBERS W/ 8d COMMONS: 6"OC AT EDGE & 12"OC IN FIELD, TYP UNO IN PLANS & DETAILS. 3. ROOFS:
- A. FOR ROOF FRAMING MEMBER SIZES & LOC(S), RE: PLAN. B. PROVIDE 5/8" APA RATED ROOF SHEATHING, TYP UNO. NAIL TO SUPPORTING MEMBERS W/ 8d COMMONS: 6"OC AT EDGE & 12"OC IN FIELD, TYP UNO IN PLANS & DETAILS. 4. OPENINGS:
- A. COORD SIZE & LOC(S) OF OPENINGS W/ ARCHITECTURAL DRAWINGS.
- B. FOR TYP OPENING FRAMING REQUIREMENTS, RE: 4 / S3.0C. FOR OPENING FRAMING, RE: WALL OPENING SCHEDULE BELOW AND PLAN.

WALL OPENING SCHEDULE

OPENING	HEADER	JACK STUDS	KING STUDS
OPNG 1	(2) 2x8 HF#2	2x6 HF#2	2x6 HF#2
OPNG 2	(2) 2x8 HF#2	2x6 HF#2	(2) 2x6 HF#2






FRAMING PLAN KEYNOTES

(1) EXISTING CEILING JOIST SPAN DIRECTION, CONTACT ENGINEER IF DIFFERENT FRAMING CONDITIONS ARE DISCOVERED

UPPER FLOOR & ADDITION ROOF FRAMING PLAN 1/4" = 1'-0"




FRAMING PLAN NOTES


- 1. WALLS: A. ALL EXTERIOR WALLS SHOWN IN PLAN ARE 2x6 HF#2 AT 16"OC, TYP UNO.
- B. PROVIDE TREATED SILL PLATE, TYP.C. PROVIDE 7/16" APA RATED WALL SHEATHING. NAIL TO
- WALL STUDS W/ 8d COMMONS: 6"OC AT EDGE & 12"OC IN FIELD, TYP UNO IN PLANS & DETAILS.
- 2. FLOORS: A. FOR FRAMING MEMBER SIZES & LOC(S), RE: PLAN.B. PROVIDE 3/4" APA RATED, T&G, FLOOR SHEATHING, TYP UNO. GLUE & NAIL TO SUPPORTING MEMBERS W/ 8d COMMONS: 6"OC AT EDGE & 12"OC IN FIELD, TYP UNO IN PLANS & DETAILS.
- 3. ROOFS: A. FOR ROOF FRAMING MEMBER SIZES & LOC(S), RE: PLAN. B. PROVIDE 5/8" APA RATED ROOF SHEATHING, TYP UNO. NAIL TO SUPPORTING MEMBERS W/ 8d COMMONS: 6"OC AT EDGE & 12"OC IN FIELD, TYP UNO IN PLANS & DETAILS.
- 4. OPENINGS: A. COORD SIZE & LOC(S) OF OPENINGS W/ ARCHITECTURAL DRAWINGS.
- B. FOR TYP OPENING FRAMING REQUIREMENTS, RE: 4 / S3.0C. FOR OPENING FRAMING, RE: WALL OPENING SCHEDULE BELOW AND PLAN.

WALL OPENING SCHEDULE

OPENING	HEADER	JACK STUDS	KING STUDS
OPNG 1	(2) 2x8 HF#2	2x6 HF#2	2x6 HF#2
OPNG 2	(2) 2x8 HF#2	2x6 HF#2	(2) 2x6 HF#2



11/13/2020 1:48:38 PM



31M 360://Naffziger Residence/20.21 - Naffziger Residence (Fort Collins, CO)

1/13/2020 1:48:39 PI